

Vigor Router 4G (WiMAX / LTE) Support List

VigorFly 210 – V1.3.5



WiMAX							
<u>Country</u>	Russia	Nicaragua	Lithuania	USA	Malaysia	Peru	
Module							
Clear 4G+ Mobile Series S			■	■			
Samsung swc-u200	■		■				
Teltonika UM6235			■				
Yota Jingle WU217	■	■					
Yota-One	■						
Infomark IMW-U300					■		
Seowon SWU-3400A							■

LTE						
<u>Country</u>	Russia	Sweden	USA	Portugal	Poland	
Module						
Huawei E392u				■		
Huawei E398*		■				
Huawei E3276		■		■	■	
LG VL600			■			
Samsung B3730		■				
Yota-One LU150	■					
ZTE MF820D		■		■		
ZTE MF821					⊙	
ZTE MF823		■			■	
ZTE MF821D		■		■		
Sierra 320U*			■			
Novatel 551L			■			

Vigor Router 4G (WiMAX / LTE) Support List

Vigor2130 Series



LTE	
Samsung B3730	V1.5.2

Vigor Router 4G (WiMAX / LTE) Support List

Vigor2760 Delight version



LTE	
Alcatel L100V	V3.7.5.2
Alcatel L800	V3.7.5.2
Alcatel W100	V3.7.5.2
Alcatel W800	V3.7.5.2
Huawei E3272	V3.7.5.2
Huawei E3276	V3.7.5.2
Huawei E392	V3.7.5.2
Huawei E398	V3.7.5.2
LG VL600	V3.7.5.2
Novatel 551L	V3.7.5.2
Novatel UML290VW	V3.7.5.2
Samsung GT-B3730	V3.7.5.2
ZTE MF823	V3.7.5.2
ZTE MF820D	V3.7.5.2
ZTE MF821D	V3.7.5.2
ZTE MF880D	V3.7.5.2

Vigor Router 4G (WiMAX / LTE) Support List

Vigor2830 Vn plus & n plus



WiMAX

Samsung swc-u200

V3.3.7.1

LTE

LG VL600

V3.3.7.1

Huawei E398*

V3.6.4

Vodafone K4201

V3.6.6.2

Vigor Router 4G (WiMAX / LTE) Support List

Vigor2860 Series



WiMAX

Samsung swc-u200	V3.7.1
-------------------------	--------

LTE

LG VL600	V3.7.1
Yota-One LU150	V3.7.1
ZTE MF820D	V3.7.4
ZTE MF821D	V3.7.1
ZTE MF821	V3.7.1
ZTE MF823	V3.7.4.2
ZTE MF880D	V3.7.4
Huawei E392	V3.7.3
Huawei E398*	V3.7.1
Huawei E3276	V3.7.4
Vodafone K4201	V3.7.4
Alcatel One Touch L800	V3.7.4
Alcatel L100V	V3.7.4.2
Alcatel L800	V3.7.4.2
Alcatel W100	V3.7.4.2
Alcatel W800	V3.7.4.2
Verizon Wireless Novatel 551L	V3.7.4
Verizon Wireless Pantech UML290	V3.7.4
Samsung GT-B3730	V3.7.4

Vigor Router 4G (WiMAX / LTE) Support List

Vigor2912 Series



LTE	
Huawei E398*	V3.7.1

Vigor Router 4G (WiMAX / LTE) Support List

Vigor2920 Series



WiMAX

Samsung swc-u200

V3.3.7.1

LTE

LG VL600

V3.3.7.1

Sierra 320U*

V3.6.3

ZTE MF821D

V3.6.4

Vigor Router 4G (WiMAX / LTE) Support List

Vigor2925 Series



LTE	
LG VL600	V3.7.4.2
Yota-One LU150	V3.7.4.2
ZTE MF820D	V3.7.4.2
ZTE MF821D	V3.7.4.2
ZTE MF821	V3.7.4.2
ZTE MF823	V3.7.4.2
ZTE MF880D	V3.7.4.2
Huawei E392	V3.7.4.2
Huawei E398*	V3.7.4.2
Huawei E3276	V3.7.4.2
Vodafone K4201	V3.7.4.2
Alcatel One Touch L800	V3.7.4.2
Verizon Wireless Novatel 551L	V3.7.4.2
Verizon Wireless Pantech UML290	V3.7.4.2
Samsung GT-B3730	V3.7.4.2

Vigor Router 4G (WiMAX / LTE) Support List

Vigor3900



LTE

Huawei E398*

V1.0.7.1

■ : This symbol indicates that the USB Modem has been tested and is supported by the router

⊙ : Note: Please connect an USB hub for a proper functionality, because this modem needs more power.

*: This modem only for the option: [3G/4G USB modem (PPP mode)]

Many of these modems, especially the LTE models, can require more power than the router can deliver. This can cause erratic behavior and frequent disconnections.

To solve this problem either use a USB Y-cable or a powered USB Hub to supply the extra power required by the modem.

RF interference from the router may also affect the modem and cause the same erratic behavior.

Using a good quality USB extension cable with ferrite bead chokes will help this in many cases.